

## 40480 QA

### Coil Power Losses Check 2023-06-26 09:33:06

---

#### [Log-File](#)

---

No measurement is performed during the Coil Power Loss Check. It only verifies that the Coil Power Loss Tune-Up has already been performed successfully.

This is done by checking the coil power loss value in the coil file. Since the default of this value is very low, it would be out of specification if no Tune-Up had been performed.

#### TALES Reference Power

	Value	Low Spec	High Spec	Unit
Coil Power Losses	3883.21			W
Sigma Phantom	2.42			
TALES Pref	1604.63	500.00	2600.00	W

TALES Pref value in specification

**Results are in specification**

---

**Program finished successfully**